

## **Excerpt from Safe Work Method Statement**

Activity	Hazard	Risk control measure	Persons responsible
Unloading materials by hand from a delivery truck	Body sprains and strains from lifting materials	Use correct lifting techniques	All personnel involved in the activity
		Get assistance when lifting heavy loads	
	Splinters or cuts	Wear gloves	As above
	Being struck by materials	Take care when moving materials by hand	As above
		Maintain an awareness of other people in the area	
	Trips and falls	Remove obstacles in pathway	As above
		Be aware of uneven or unstable surfaces	